



Q at booth = 225 cfm/ft² open area
 Q at bottom = 350 cfm

Minimum duct velocity = 4000 fpm

$h_e = 1.75 VP_d$, at point A



TITLE

METAL CUTTING BANDSAW

FIGURE

VS-45-01

DATE

10-90