



$Q=300 \text{ cfm/ft}^2$ of open area
 Minimum duct velocity = 3500 fpm
 $h_e = 0.35 VP_d$

Reference 10.45.4



TITLE
 HIGH TOXICITY MATERIALS
 MILLING MACHINE HOOD

FIGURE VS-45-02
 DATE 11-90