



Notes: 20 air changes per minute  
 At least 500 fpm inward velocity at all openings  
 Minimum duct velocity = 4000 fpm  
 If cabinet has self-contained dust collector,  
 consult manufacturer for losses.  
 $h_e = 1.0 VP_d$



TITLE

ABRASIVE BLASTING  
CABINET

FIGURE

VS-80-02

DATE

02-91