



$Q = 150 \text{ cfm/ft}^2$  of gross bench area  
 Minimum duct velocity = 4000 fpm  
 $h_e = 1.78 VP_s + 0.25 VP_d$



TITLE

**TORCH CUTTING  
VENTILATION**

FIGURE

**VS-90-10**

DATE

**1-91**