



$Q = 400 \text{ cfm/ft}^2 \text{ of opening}$
 Minimum duct velocity = 3500 fpm
 $h_e = 1.78 VP_s + 0.25 VP_d$



TITLE

MELTING FURNACE
ELECTRIC ROCKING

FIGURE

VS-55-04

DATE

2-91